To: Wands, James[James.Wands@hdrinc.com]

Cc: John Connolly[jconnolly@anchorqea.com]; Robert Law[rlaw@demaximis.com]; Naranjo,

Eugenia[Naranjo.Eugenia@epa.gov]

From: Peter Israelsson

Sent: Fri 9/20/2013 5:24:05 PM

Subject: Lower Passaic River - 2378-TCDD surface mapping files

surf TCDD shapefiles 20130920 LPR.zip

ProbPlot 1995 vs 2010 data by mapped group 20130920.pdf

James -

I am transmitting the requested information regarding the CPG's surface sediment 2378-TCDD mapping. Each attachment is explained below.

- 1. Shapefiles of 2,3,7,8-TCDD contaminant map for the LPR □ surf_TCDD_shapefiles_20130920_LPR.zip
- b. "2010" surface (using the 2007-2012 dataset) \(\square\) surf_TCDD_2010_20130920_LPR.shp
- 2. Areas of the groups (see 5/17/2013 mapping memo for definition details):

100		Area	Area
Groups	Deposition Characteristics	RM 1 to RM 7	RM 0 to RM 7.5
		(acres)	(acres)
Group 1	Shoals	155	369
Group 2	No historical deposition	21	21
Group 3a	Little to moderate historical deposition; ≥1ft erosion 1995 to 2012	14	14
Group 3b	Little to moderate historical deposition; <1ft erosion 1995 to	41	41

- 3. Probability distributions and counts of contaminant data in each mapped dataset, by mapping group
- a. ProbPlot_1995_vs_2010_data_by_mapped_group_20130920.pdf

Please let me know if you have any questions.

Have a good weekend,

Peter

Peter H. Israelsson, PhD

ANCHOR QEA, LLC

Note: new office address as of June 2013

10 Liberty Square, Sixth Floor Boston, MA 02109, USA T +1.857.991.1111, ext 1003 M +1.617.686.4149

ANCHOR QEA, LLC www.anchorgea.com

Please consider the environment before printing this email.

This electronic message transmission contains information that may be confidential and/or privileged work product prepared in anticipation of litigation. The information is intended for the use of the individual or entity named above. If you are not the intended recipient, please be aware that any disclosure, copying distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us by telephone at (617) 547-3830.